



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

0001

Inspection Report

Minerals Regulatory Program

Date: March 11, 2009

Reviewed: 

Mine Name: Diamond Mountain Resources	Permit Number: M/047/0066
Operator Name: Deseret Generation & Transmission	Inspection Date: 09-17-2008
Inspector(s): L Heppler	Time: 11:00 AM
Other Participants: Mine	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 11-29-2008 **Bond Amount:** \$275,000 **Permit fee** \$500 due - invoice sent out 06/20/2009

Purpose of Inspection: Routine annual Inspection, last inspection 04/19/2007

Inspection Summary: Mine disturbance is limited. No concurrent reclamation has been started but area is tight around the operation. Photos were taken to document site conditions.

Conclusions and Recommendations: Bond amount needs to be escalated. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Larry Jorgensen

NFS - DAHerron@fs.fed.us

O:\M047-Utah\M0470066-DG&T\inspections\insp-09172008.doc

0001

